

Box Maker - Mehr Boxes

Box Dimensions Inside

X axis lenght

Y axis lenght

Z axis lenght

Tab Options

Tab Mode amount

target tab size

Tabs in X axis

Tabs in Y axis

Tabs in Z axis

Material Options

Material Thickness

Beam diameter

Space Between Parts

Live preview

Draw left side (YxZ)

Draw right side(YxZ)

Draw front side (XxZ)

Draw back side (XxZ)

Live preview

Box Maker - Mehr Boxes

Sizes **Draw sides** Compartments

Compartments on the X Axis

X Compartments

Mode even

Distances

fit axis lenght to compartments


Compartments on the Y Axis

Y Compartments

Mode even

Distances

fit axis lenght to compartments



Version #1

Erstellt: 2025-05-24 15:19:59 CEST von Mario Voigt

Zuletzt aktualisiert: 2025-05-24 15:20:20 CEST von Mario Voigt